| FD-36 (Re  | ev. <b>8</b> -26-82)                            | . 15   |   |         |
|--|---|--|---|---------|
|  | TRANSMIT VIA:  Teletype Facsimile AIRTEL        | FBI PRECEDENCE: Immediate Priority Routine                                     | CLASS ON:  TOP SECRET  SECRET  CONFIDENTIAL  UNCLAS E F T O |         |
| Park Control of the C | ALL INFORMATI<br>HEREIN IS UNO<br>DATE 07-08-20 |  | UNCLAS  Date 3/3/86   |         |
| Asset.   | TO:<br>FROM:                                    | DIRECTOR, FBI (163A-NEW) SAC, MIAMI (163A-4162)(P)(                            | (C-1)   | ,       |
|  | GANDER, DECEMBEI FOREIGN                        | · ·  | JEN   |         |
|  |   | Re Miami airtel to the Bur   | reau dated 2/12/86.   | · .     |
| P. C.  | self-ex   | planatory LHM captioned as a   |   |         |
|  |   |  | ,   | (FO = 7 |
|  | l — Mia<br>HWP/mcq                              |  | W-131 N/63-56/6   | b7C     |
|  | furnished L<br>DIA PENTI                        | the copy of LHM  TO TOM RAUTER  TO TOM RAUTER  TO GON BY LIAISON  TO GON BY MY | Clause Wint   |         |
| STUTE.   | Approved:                                       | Transmitted  | - 1* -  (Number): (Time)                                    |         |
|  | JUNDANS   | untohiais & Miller aissemination Con 3/18/20 Con                               | ATO   |         |

| In this regard, SSA Fugitive/General   |  |  |  |
|--|--|--|--|
| Government Crimes Unit is coordinating a letter response to  |  |  |  |
| over Mr. Mintz' signature advising of an FPC   |  |  |  |
| investigation and referring him to the   |  |  |  |
| Washington, D.C., for the results of its investigation of the  |  |  |  |
| Arrow Air incident.  |  |  |  |
| This matter was coordinated with  Chief, Information and Privacy Acts Litigation Unit, Legal Council Division. |  |  |  |
| Enclosure  |  |  |  |

#### ARROW AIR DC 8-63

and several ground support personnel at CIA.

observed that there would have been no reason to reopen that door at either Cologne or Gander, Newfoundland. However, he does not know for a fact whether or not the cargo door was reopened prior to the aircraft's departure from Gander, Newfoundland on December 12, 1985.

b6 b7С

b6

b7C

- 3. The engine anti-ice valve on the number one engine, was inoperative when activated on encountering ice while on descent into Cologne, West Germany. \_\_\_\_\_\_\_ is not aware of whether \_\_\_\_\_\_ resolved the problem or tagged it for maintenance. Likewise, he is unaware of whether \_\_\_\_\_\_ briefed his \_\_\_\_\_\_ but presumes he did so.
- 4. It had been noticed that the number four engine was running somewhat hotter than the other three, but was still within limits.
- 5. Fresh water from the aft lavatories was leaking from the fuselage.
- 6. had noticed during the Cairo to Cologne flight on December 12, 1985, that there was a deficiency in the hydraulic fluid.

On arrival at Cologne, while parked at the gate usually occupied by AA, the number of which could not recall, he noticed a mechanic from which usually performed the service on the AA, reviewing the log in the cockpit regarding the hydraulic problem. He presumes that the mechanic thereafter added hyraulic fluid to the system.

There were no other discrepencies known to and no other service or maintenance performed on the aircraft on December 11, 1985, other than refueling and restocking the galleys.

In Cologne, the aircraft departed from and landed at the COLOGNE - BONN INTERNATIONAL AIRPORT (CBIA).

In Cairo, the aircraft landed at CIA and was parked at remote stand, believed to be number nine, the parking space usually occupied by AA aircraft at CIA.

Other than one uniformed soldier carrying a weapon, there was no other visible security at the CIA. All of the ground service on the aircraft was done by Egyptian

ARROW AIR DC 8-63

personnel. He and the other crew members stayed with the aircraft during its stay in Cairo. During that period of time, he noticed 20 or more persons milling about the aircraft with no apparent function in servicing it. At no time in Cairo did he or any other member of the crew become suspicious of any of the individuals milling about the aircraft.

At the CBIA, there was what \_\_\_\_\_ characterized as the usual tight German security, however, there was no special security detail for the AA aircraft.

The conversation between his crew and the crew relieving him, headed by was casual. He does recall a comment that they were running heavy. This comment was based upon the fact that he and after reviewing the personnel and equipment placed on board, estimated that their weight was slightly higher than on the manifest, but certainly not over maximum gross weight.

had calculated 170 pounds per passenger, and 100 pounds per duffel bag.

As he recalls on the Cairo to Cologne run, they departed with approximately 95,000 pounds to 100,000 pounds of fuel, out of a maximum capacity of 165,800 pounds. While he has no certain knowledge he estimates that the Cologne to Gander flight would have departed with approximately 120,000 pounds of fuel. While the final leg departing Gander would have required no more than 70,000 pounds of fuel.

does not recall or any member of his crew mentioning any discrepencies or deficiencies on the aircraft, when his crew relieved them early on December 11, 1985, at Cologne.

observed that maintenance was never the "strong suit" of AA, but he never observed aircraft flown with major discrepencies effecting the airworthiness of the ship. Maintenance for the AA aircraft were performed by BATCH AIR (BA), of Miami, Florida, which was owned by the same individual who owned AA.

feels this arrangement detracted from the maintenance program at AA.

has discussed the foregoing with a representative of the Canadian board investigating the accident, both by telephone from Cologne, Germany immediately after the

b6 b7с

b6

ARROW AIR DC 8-63 accident and again in person at Miami, Florida, during early February, 1986. provided a copy of a Crew Member Pay and Expense Form, executed by him for flights during December, 1985, as well as a computer time record provided to him by AA, for the period November 16, 1985 through December 15, 1985, copies of which are attached hereto. furnished the following personal data during the course of interview: Full Name: Address: Florida Mailing Address: Florida Telephone Number: Race: White Sex: Male Date of Birth: Height: 5'11" tall Weight: 190 pounds Color of Hair: Brown Color of Eyes: Green Marital Status: Current Employment: Florida Prior Arrests: None claimed Military Service: United States Coast Guard, through\_\_\_\_ non-pilot aircrew member Serial Number:

b6

b6

b6

b7C

He is

His

b7C

b7C

- 1 -

The records of the FEDERAL AVIATION ADMINISTRATION (FAA),

holds an

and certified mechanic.

and his Social Security

Oklahoma City, indicates

Pilot Certificate Number is

Account Number is listed as

also a

64

MM 163A-4162

| Thereafter |
|------------|
| ng to      |
|            |
|            |
| lead       |
|            |



# U.S. Department of Justice

# Federal Bureau of Investigation

In Reply, Please Refer to File No.

February 12, 1986 Miami, Florida ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED DATE 07-08-20@9 BY 60324 UCBAW/DK/SBS

RE: ARROW AIR DC 8-63

GANDER, NEW FOUNDLAND, DECEMBER 12, 1985;

FOREIGN POLICE COOPERATION

| On January 31, 1986, a Special Agent (SA) of the Federal         |
|--|
| Bureau of Investigation (FBI) contacted and interviewed          |
| ARROW AIR, 7955 N.W. 12th Street, Fourth Floor,                  |
| Miami, Florida, telephone made available                         |
| the names and addresses of the following ARROW AIR flight crew:  |
| the names and addresses of the following mater and tright crow-  |
|  |
| Florida  |
| Telephone Number:  |
|  |
|  |
| <del> </del>   |
| Florida  |
| Telephone Number:  |
|  |
|  |
|  |
| California   |
| Telephone Number:  |
|  |
| •  |
| stated he was willing to cooperate in any matter                 |
| necessary and advised that all of the members of the flight crew |
| had  |
|  |
|  |
|  |
|  |

This document contains neither recommendations nor conclusions of the FBI. It is the property of the FBI and is loaned to your agency; it and its contents are not to be distributed outside your agency.

163 56160 -2 ENCLOSURE

FBI/DOJ

b6 b7c

| TRANSMIT VIA: ☐ Teletype   | FBI PRECEDENCE: Immediate   | CLASSIFICATION:  TOP SECRET   |                         |
|--|-----------------------------|---|-------------------------|
| ☐ Facsimile ☐ AIRTEL  ALL INFORMATION CONTAI                             | □* Priority □ Routine       | <ul><li>□ SECRET</li><li>□ CONFIDENTIAL</li><li>□ UNCLAS E F T O</li><li>□ UNCLAS</li></ul> | -                       |
| HEREIN IS UNCLASSIFIED DATE 07-08-2009 BY 603                            | 324 UCBAW/DK/SBS            | Date 3/3/86   |                         |
|  |                             | IERAL GOVERNMENT CRIME  | ES UNIT,                |
| FROM: SAC, I<br>ARROW AIR DC 8-6<br>GANDER, NEWFOUND<br>DECEMBER 12, 198 | OLAND,                      | RUC)  |                         |
| FOREIGN POLICE ( GENERAL CRIMINAL BUDED: 2/21/86 (OO: BUREAU)            | COOPERATION -<br>L MATTERS; | _ 56160-2   |                         |
|  | ami airtel to the Bu        | reau 2/12/86.   | * .                     |
| copies of an LHI<br>Legat, Ottawa.                                       | 4 suitable for disse        |   | through                 |
|  | A mentioned in enclo        | osed LHM was SA   |                         |
| on 3/19/BL LHM formished LTC  DIA Pentagon by Li                         |                             | 165 5   | 66<br>b7c<br>b7D<br>(2) |
| 3 - Bureau (Enc. (2 - <del>Legat. (</del><br>1 - Miami WPS:mcb           |                             | LIGUSON<br>CLINIT 12 MAR 1  | 0 1986                  |
|  | 1* >                        | 71 42 4   | 188 April               |
| Approved:  | 2007                        | mber) (Time)  |                         |
| Scis NAMI to LI  |                             | U.S. GOVERNMENT PRINTING OFFIC  | E: 1984 O - 449-465     |



# U.S. Department of Justice

#### Federal Bureau of Investigation

employed by ARROW

In Reply, Please Refer to File No.

Miami, Florida March 3, 1986

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED DATE 07-08-2009 BY 60324 UCBAW/DK/SBS

ARROW AIR DC 8-63 GANDER, NEWFOUNDLAND DECEMBER 12, 1985

| AIR, residing at  |
|---|
| Florida, home telephone was interviewed by  |
| a Special Agent of the FEDERAL BUREAU OF INVESTIGATION (FBI)  |
| on February 22, 1986, and he gave essentially the following   |
| information: , (i)  |
| A commence of the commence of |
| I. Concerning the condition of the ARROW AIR DC8-63   |
| tail number N950JW, during its round trip from Cologne, West  |
| Germany to Cairo, Egypt, and return, during the period  |
| December 11-12, 1986, noted only five   |
| items that could have indicated potential operational problems  |
| but were not considered to be sufficiently significant to   |
| justify grounding the airgraft  |

First, the incoming crew who turned the aircraft over to him in Cologne on December 11, 1985, advised him of an overburn of fuel in the amount of 3,000 to 4,000 pounds during their incoming trip. Fuel overburns result from such things as overweight, control surfaces (flaps) not streamlined, leaking door seals, and headwinds. He did not fly overweight in either direction. He experienced the same amount of overburn during his round trip; it remained constant during both legs of the trip. He considered this as insignificant because it amounted to only 4 percent to 4.5 percent of the fuel load, and it remained constant.

163-56160-21

FBI/DOJ

b6 b7C

| Second, during pre-flight operations while taxiing the aircraft toward take-off at Cologne, he felt a soft ratcheting of the elevator control during its last inch of forward travel.  "It felt like a soft strumming of four of your fingers against a finger of your other hand," he said. He stopped the aircraft and performed this operation again. The then advised him that this problem with this aircraft had been written up previously, and WORLD AIRWAYS, Oakland, California, had checked it out thoroughly. ARROW AIR's European Manager of Operations was in the cockpit at that time and he told to have a mechanic look into this matter upon return of this aircraft to Cologne on December 12, 1985. Later, during the return flight from Cairo to Cologne, the captain reminded the flight engineer to have a mechanic at Cologne examine the tail compartment. |
|---|
| Third, noticed that this air-craft climbed slowly, but he added that this is "not too unusual" for this type aircraft. "It is not a high performance aircraft," he said. The climb rate was constant on both legs of the trip. There was no problem with the flow of fuel to the engines or any other discerned problem that may have contributed to the slowness of the climb rate. He thought no more about it because this aircraft appeared to be operating normally.   |
| Fourth, the right outboard engine (the number four engine) was old and was scheduled to be replaced with a new one after the Cologne-Newfoundland-Kentucky trip. WORLD AIR-WAYS, Oakland, California, already had the new engine and would have installed it if the aircraft had not crashed. The only discernable problem with the old engine was that its exhaust gas temperture was 15°-20° higher than the other three engines  |
| while in flight. This was not significant in  |
| opinion. However, after take-off from Cairo on the return leg of the trip, the flight engineer told him that during take-off, the temperature differential had been 50° and because of that, the flight engineer had pulled back the number four engine throttle slightly, to reduce this temperature.  did not report this problem, because he knew the old engine was soon to be replaced, and the 15°-20° difference was insignificant. Furthermore, all commercial airline pilots are higly trained and skilled in the procedures to be performed instantly upon loss of an engine during take-off and flight.  |

b€ b7C

b6 b7C

Fifth, while en route from Cairo to Cologne on December 11, 1985, noticed that the hydraulic fluid instrument in the cockpit indicated that the reservoir was slightly less than full. He believes that he wrote it up after arrival at Cologne on December 12, 1985. He estimated that four quarts of hydraulic fluid should have been added to the reservoir in Cologne. He said that the hydraulic pressure was normal during both legs of his trip, therefore, no leak of fluid was indicated. He considered the four quarts to be an insignificant amount, because the reservoir holds 20 quarts, and the entire system holds 40 gallons.

II. Concerning his actual flight schedules of his Cologne-Cairo-Cologne round trip on December 11 - 12, 1985, recorded the exact times, in Greenwich Mean Time (ZULU), that he released the brakes and set the brakes at those cities. The times were as follows:

Cologne 1050Z, December 11, 1985 Cairo 1534Z, December 11, 1985 Cairo 2035Z, December 11, 1985 Cologne 0121Z, December 12, 1985

observed that the crew was rested, clean and not rushed at the beginning of both legs of his flight. Further, he commented that he and his crew flew this same aircraft on the same round trip on December 4, 1985, and those flight times were recorded, in like manner, as follows:


Cologne 0047Z, December 4, 1985 Cairo 0512Z, December 4, 1985 Cairo 1130Z, December 4, 1985 Cologne 1625Z, December 4, 1985

III. Concerning the two airports, the Cologne airport is used by civilian traffic, but the Cairo airport is for both civilian and military traffic. In Cairo, there were large numbers of both Egyptian and Russian military aircraft which were parked in the military area of the airport. The designated military area was 400 yards from assigned parking place in the civilian area. There is no fence between the civilian and military area, but they are separated from one another by runway 16/34. On December 11, 1985, he parked his aircraft on the north side of the terminal building, in parking space number 7, facing northwest.

b6

b7C

b6



bЕ

- vii. In addition to his answers to the preceding six specific questions, volunteered the following comments:
- A. Virtually every aircraft in existence has Deferred Maintenance Items (DMI). In 35 years, he has flown only one aircraft that had no DMI. He has flown aircraft with as many as 20 DMI. DMI's demand judgment calls of each captain, all of whom must check maintenance logs before flights and judge whether to fly, whether to have any DMI repaired before flight, or whether to consider them insignificant to the flight being planned at the moment.
- B. Regarding an alleged DMI concerning a de-icing valve on N950JW, he does not remember such a DMI. There are three icing valves on each engine, each with a different function. Also, there are warning lights in the cockpit to alert the crew if any of the valves are not working.
- C. Regarding an alleged problem with instruments that control the plane's ability to climb, descend and turn, he said that instrument is called a Gyro Horizon. There are three of these in a DC-8, each with a different source of electric power. One of them, for example, has a Honda battery so that it will continue to function in case all electric power throughout the aircraft fails. When any one of these Gyro Horizons fail, a warning flag appears as a signal to the crew to not respect information that it is giving.

b€ b7C

b6 b7C

E. The December 11-12 flight of N950JW was not overloaded on any leg of its flight. The weight of passengers and baggage on board fell within normal limits for this aircraft established by the FEDERAL AVIATION AGENCY (FAA). In fact, the gross weight of this aircraft was greatest when it departed Cologne, en route to Gander, Newfoundland. The fuel weights during the fatal flight were as follows:

86,000 pounds out of Cairo 119,000 pounds out of Cologne 101,000 pounds out of Gander

- F. Jet engines function better in lower temperatures. The temperatures at take-off times of the fatal flight were as follows:
  - + 15°C at Cairo
  - + 6°C at Cologne
    - 0°C at Gander
- G. Six empty food transporters were taken out of "B" belly in Cologne and presumably, were replaced with full ones by LUFTHANSA catering service for the Cologne-Gander leg. These food transporters are never searched.

H. flying experience includes flying for AIRLIFT
INTERNATIONAL and flying for ARROW AIR. He has flown various legs of the trip described as Cairo-Cologne-Gander-Kentucky and other destinations 20 times. He also served in the U.S. Navy.


b6

b7C

I. theorized that the crash of N950JW at Gander was caused by either structural failure of the aircraft on take-off, or explosion of a bomb that may have been placed in the aircraft in Cologne on December 12, 1985. He said that in his opinion, the loss of the number four engine would not have caused the crash. He added that he believes that the right wing "stalled" causing the nose to rise and the aircraft to roll onto its right side. This action would cause the aircraft to veer to its right and begin immediate If the "stall" were not corrected by the crew, the descent. aircraft would crash and skid on the ground toward its left. It is his understanding that this is precisely what happened to N950JW. He further theorized that the force of an explosion of a bomb in "B" belly could have "Kicked up the slightly lowered flaps on the right wing," causing the wing to stall.


J. In conclusion, made available a sketch of his theory described above, and also three pages from his pilots airport guide book, demonstrating the places N950JW parked in Cairo and Cologne on December 11 and 12, 1985, and his understanding of the crash site at Gander. These pages are as follows:

b6















GANDER, NFLD. CYQX (11-1) MAY 4-84 JEPPESEN GANDER INT'L GANDER Ground 121.9 GANDER Departure (R) 128.5 N48 56.4 W054 34.2 357.2°/2.8 From YQX 112.7 Tower 118.1 Elev 496' Var 26°W · VOT 114. 54-37 54-32 - 48-58 NOTE: Airport of entry. ●550¹ -48-57 •547' EXTREMELY NOSE HIGH RTWINGLOW - 48-55 USABLE LENGTHS LANDING BEYOND— Threshold | Glide Slope **RWY** HIRL HIALS RVR 9300' 10,200 200' HIRL ALS REIL VASI-L (3 bar) 10,200 <sup>09</sup>0 <u>27</u> HIRL 3200' 200' 3200' HIRL ALS HIRL HIALS RVR 7899' 200' HIRL ALS REIL **②**VASI-L (3 bar) 1 Limited to 42,000 lbs. Usable days only. 2 Upwind angle 3.0°, downwind angle 2.75°. FOR FILING AS ALTERNATE TAKE-OFF **DI** All Rwys Non-Precision Precision Landing Minimums Apply.
Use Ceiling (HAT/HAA Equivalent) & Vis
of Rwy to be Used in Event of Return. 600-2 800-2 ER RVR 16 or 1/4 authorized for AY, EA, FT, LY, OA, PAA, TW, KU. O 1983 JEPPESEN SANDERSON ALL RIGHTS RESERVED CHANGES: See other side.



E RT FLAP (INBOARD GOUTS) SEGMENT BELLY FLAP

| ∢ FD-3€ (Ŗev. 8-26-82) |   |   |   | - A - A  |
|------------------------|---|---|---|--|
| Kir i Air              | TRANSMIT VIA:  ☐ Teletype ☐ Facsimile  XXAIRTEL   | PRECEDENCE:  Immediate  Priority Routine  | CLASSIFICATION:  TOP SECRET SECRET CONFIDENTIAL UNCLAS E F T O  |  |
| _                      |   | CTOR, FBI   | UNCLAS Date 3/25/86   |  |
| 18/26/1                | FROM: PIN ACT   | SAN FRANCISCO (163A-  | GOVERNMENT CRIMES UNTI  | CID, FBIHQ)  |
| pholips                | DECE<br>FORE<br>GENE<br>BUDE  | er, Newfoundland,<br>MBER 12, 1985;<br>IGN POLICE COOPERATIO<br>RAL CRIMINAL MATTERS;                                       | N,  |  |
|                        | Re M  | iami airtel to the Bu   | neau, 2/12/86.  |  |
| 1 Classic              | of an LHM sett Special Agent captioned matt was experience residence in out of the are immediately af | ing forth results of er. It should be not d in contacting Arrow California a a for extended period ter such interview wa at | s his employment keéps<br>s of time. Additiona  | concerning difficulty at his s him lly, b6 b7C b7D |
| DE                     | flu, and this date.   | matter is being repor readily agreed that t disseminated to a fri   | ted at the earliest potential the information as furnered to the second | ossible<br>nished                                  |
|                        | Bureau (En 1 - San Franci DJS/mas (3)  CSAHWADINUOL for dissertination 1                              | sco (163A-2554)   | 12 MAR 3:   | 1986   |
| nche to                | Approved:   | Transmitted   | Per   | // Die /   |
| j                      | ICC4 HARCE  | (Num  |   |  |
| 2                      | Hemiles   | 1028  | ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED  |  |

DATE 07-08-2009 BY 60324 UCBAW/DK/SBS

In Reply, Please Refer to



File No.

## U.S. Department of Justice

Federal Bureau of Investigation

San Francisco, California

California, **1**aboard

March 25, 1986

ARROW AIR
DC8-63,
Gander, Newfoundland,
DECEMBER 12, 1985;

advised on March 3, 1986 that he was the Arrow Airlines DC8, registration no. N950JW, when the plane was flown from Cologne, West Germany to Cairo, Egypt on December 11, 1985, and subsequently returned to Cologne, West Germany on December Shortly after its arrival at Cologne, West Germany 12, 1985. the responsibility for the plane was turned over to the crew who thereafter died in the fatal crash of the airplane at stated that Gander, Newfoundland on December 12, 1985. the airplane was, at the time of his flight from Cologne to Cairo and return to Cologne, operating in a basically adequate manner. opinion, the airplane was operating acceptably and approximately the same way it had been for two months prior to the crash. The plane had previous problems, but log book indicates that these problems had been fixed at the Oakland, California Airport by World Airways Service Department. Because of the delay experienced when the plane was being fixed by World Airlines in Oakland, California it was running a day late of the original schedule. stated that while assigned as the Flight Engineer of the crew assigned to this airplane just prior to the crash, they left Cologne, West Germany at 10:50 a.m. (Zulu time) on December 11, 1985, arriving in Cairo, Egypt at 15:34 (Zulu time) on December 11, 1985. That they then departed Cairo, Egypt at 20:35 hours (Zulu time) on December 11, 1985, and arrived back in Cologne, West Germany at 1:21 (Zulu time) on December 12, 1985. During this trip noted that the no. 4 engine was running approximately forty degrees hot, but stated that this is not considered to be a major problem and nothing else having to do with the operating efficiency of the plane appeared to be in any way defective. This document contains neither recommendations nor conclusions of the FBI. It is the property of the FBI and is loaned to It and its contents are not to be distributed your agency. outside your agency.

h6

ARROW AIR DC8-63, Gender Newfoundland; DECEMBER 12, 1985 FOREIGN POLICE COOPERATION; GENERAL CRIMINAL MATTERS stated that both the Cologne, West Germany and Cairo, Egypt International Airports are both commercial airports. stated that the airplane required no maintenance or servicing during the period that he was assigned as part of the crew. He stated that the stops at Cologne and Cairo International Airports were for the purpose of refueling, crew changes, stated that at both Cologne and and passenger changes. Cairo International Airports the military company commander assigned three or four military men to stand by and act as guards to ensure security of the plane at both locations. stated that the military personnel which were aboard the airplane in the flight from Cologne, West Germany got off the airplane at Cairo, Egypt, and , the airplane's co-pilot, as well as all of the flight attendants, supervised the Egyptian crews who were assigned to off-loading the plane's stated that it was normal to have Egyptian cargo area. personnel do the off-loading of the planes pursuant to an agreement between the Egyptians and one United States Major Carpenter, the liaison officer at the Airport between the United States and Egyptian Governments. \_\_\_\_\_ characterized the security of the airplane at Cologne, West Germany as "good;" characterized whereas the security of the airplane at Cairo, Egypt he classified as being "standard," although he added that he saw nothing out of the ordinary at either the West German or Egyptian Airports. could not recall either receiving any pertinent information from the previous crew of the airplane, nor the giving of any pertinent information to the crew which relieved the crew of which he was a member. stated that all of the above In conclusion, information had been given by him to a Canadian National Transportation and Safety Board Agent who had telephonically

b6

b6

b6

b7C

|within

b7C

for approximately one hour each.

days of the crash of the airplane and had interviewed both

could furnish no additional information at this time.

made contact with both himself and

ALL INFORMATION CONTAINED N IS UNCLASSIFIED DATE 37-08-2009 BY.60324 UCBAW/DK/SBS

Hughes Hubbard & Reed 1201 Pennsylvania Avenue, N. W. Washington, D. C. 20004

ONE WALL STREET NEW YORK, NEW YORK 10005 212-709-7000

. 555 SOUTH FLOWER STREET LOS ANGELES, CALIFORNIA 90071 213-489-5140


April 4, 1986

47, AVENUE GEORGES MANDEL 75116 PARIS, FRANCE

4-553-9901

**QUISIDE SOURCE** 

b€ b7C



TELEPHONE: 202-626-6200

TELECOPIER: 202-347-1781

TELEX: 892674

Mr. Floyd Clark Assistant Director for Criminal Investigations Federal Bureau of Investigation J. Edgar Hoover Building Tenth and Pennsylvania Avenue, Northwest Washington, D.C. 20530

Dear Mr. Clark:

The undersigned represents Arrow Air, Inc., in the litigation arising out of the December 12, 1985, crash of an Arrow DC-8 aircraft at Gander, Newfoundland, Canada.

Following the accident it was brought to our attention that the Federal Bureau of Investigation (FBI) may have bee involved in some sort of investigatory activities relative to the accident. In this regard, we would appreciate receiving, if possible, any information relative to the nature and scope of the FBI's investigation of either the accident or surrounding circumstances, DE-149 / 6 -2

In connection with the foregoing if I can provide any additional information, please do not hesitate to call me at the above-referenced number. I very much appreciate your cooperation.

Very truly yours, b6 NO ACK per 4/11/86

64 SEP 9 1200

|  | " <b>*</b> ,   |
|--|--|
| RECEINED   |  |
| FORMS. TEXT HAS 1 DOCUMENT   | Emoc. A9-Adm. 5  |
| INBOX.11 (#4380)   | Erro. AD-LES   |
| ESTAPPE COLLABORATION OF THE STATE OF THE ST | Asst. Gir.:<br>Adm. Forvs. FC  |
| TEXT: VZCZWFO 022  | Com. tav.  |
| ALL INFORMATION CONTAINED  | happethan  |
| DATE 07-08-2009 BY 60324 UCBAW/DK/SBS  | Life trans   |
| DEWFO 022 0942120  | g Gal decay  |
| ZNR UUUUU  | Problemia  |
| R 04 2000Z APR 86  | Tech. Servs.   |
| FM: SAC, WASHINGTON FIELD (47-0)   | Telephone Rm.  |
| TO: DIRECTOR, FBI (ATTN: SSA FUGITIVE AND GOVER  | Director's Sec'y b6 NMENT b7C  |
| CRIMES UNIT, CRIMINAL INVESTIGATIVE DIVISION) ROUTINE  |  |
|  |  |
| SAC, MIAMI ROUTINE   | ,  |
| BT (O) AMTEW AIR   | ,  |
| UNCLAS   |  |
| UNSUBS: POSSIBLE IMPERSONATION OF FBI SPECIAL AGENTS; AR   | ROW  |
| AIRLINES- VICTIM, OO:MIAMI.  | 17%  |
| TITLE CHANGED TO REFLECT MIAMI AS OFFICE OF ORIGIN.  |  |
| FOR INFORMATION OF MIAMI, ON 4/1/86, WFO CONTACTED   | (Kan)  |
|  | Val  |
| ATTORNEY, HUGHES, HUSBAND, REED,   |  |
| SUITE 300, 1201 PENN. AVENUE, N.W., WDC, AT THE DIRECTION OF   | ľ  |
| HAD, EARLIER CONTACTED THE BUREAU AND REQUESTED BE   | 63-56160-  |
| INFORMED IF THE BUREAU HAD AN ONGOING INVESTIGATION REGARDING  | b6   |
| ARROW AIRLINES. FURTHER, HE ADVISED THAT HIS OFFICE HAD BEEN   | <b>21 APR 15 1986</b> b70  |
| ADVISED BY AIRLINE PERSONNEL THAT THEY HAD BEEN QUESTIONED BY  | Standard and Appendix and Appen |
| INDIVIDUALS, WHO IDENTIFIED THEMSELVES AS FBI AGENTS.  |  |
| DEC 1 2 1986 PV  | no las   |
| all breview C  | onvicting otens;   |
| Janane dec la late   | The H  |
| 1 I resultable of  | interestite, and   |
| DEC 1. 2 1986 RV   | Haller Glasey get  |

PAGE TWO DE WF 0022 UNCLÁS QUESTIONED WHETHER THESE INDIVIDUALS WERE IN FACT FBI AGENTS. WAS ADVISED THAT WFO KNEW OF NO INFORMATION REGARDING ANY INVESTIGATION OF ARROW AIRLINES. WAS DIRECTED TO CONTACT THE OFFICE OF THE ASSISTANT DIRECTOR, CID, REGARDING INFORMATION CONCERNING OTHER FBI FIELD OFFICES. ON 4/4/86RECONTACTED WFO AND PROVIDED ADDITIONAL INFORMATION. HE STATED THAT AT LEAST THREE PILOTS FOR ARROW AIRLINES HAD REPORTEDLY BEEN INTERVIEWED IN MIAMI, FLORIDA, BY INDIVIDUALS WHO IDENTIFIED THEMSELVES AS FBI AGENTS. THESE INTERVIEWS OCCURRED IN JANUARY OR FEBRUARY, 1986. INTERVIEWED WERE (X) (FNL) ARROW AIRLINES, (X)(FNU) (X)(FNU) ARROW AIRLINES. INDIVIDUALS WERE QUESTIONED REGARDING ACCESS TO CARGO AREAS, INFORMATION REGARDING ANY EXPLOSIVES ABOARD AIRCRAFT AND AIRCRAFT HYDRAULIC SYSTEMS. IN ADDITION, STATED THAT HE HAD BEEN IN CONTACT WITH THE NATIONAL TRANSPORTATION SAFETY BOARD, WHICH HAS INFORMED ARROW AIRLINES THAT AFTER THE CRASH OF THEIR MILITARY CHARTER FLIGHT IN CANADA, NTSB RECEIVED NUMEROUS REPORTS OF EXPLOSIVES BEING CARRIED ABOARD THIS AIRCRAFT. THESE REPORTS WERE ALL REPOREDLY REFERRED

TO THE FBI.

b6 b70

b6 b7C

b6 b7C

| STATED THAT HE HAD NO ADDITIONAL DETAILS REGARDING                  |
|---|
| THIS MATTER. HE ADVISED INTHE NEAR FUTURE HE WILL BE TRAVELING      |
| TO OTTAWA, CANADA, WHERE HE WILL MEET WITH                          |
| AND AT THAT TIME, HE WILL OBTAIN THEIR FIRST NAMES AND              |
| APPROPRIATE ADDRESSES. THIS INFORMATION WILL THEN BE FURNISHED TO . |
| WFO. UPON RECEIPT OF THIS INFORMATION, WFO WILL ADVISE THE BUREAU   |
| AND MIAMI.  |
| LEADS. MIAMI. AT MIAMI, FLORIDA. (1) WILL CONDUCT INDICES           |
| CHECK ON (FNU) AND (FNU)  |
| (2) WILL ADVISE THE BUREAU OF ANY INVESTIGATION CURRENTLY           |
| UNDERWAY OR HAVING BEEN CONDUCTED REGARDING ARROW AIRLINES.         |
| MIAMI SHOULD NOTE THAT WFO WAS INSTRUCTED TO PROVIDE REQUESTED      |
| INFORMATION TO THE BUREAU BY 4/8/86.                                |
| BT  |
| #0022   |

PAGE THREE DE WF 0022 UNCLAS

NNNN

| and the second s |   | Exec. 10-Adm                      |
|--|---|-----------------------------------|
| FORMS.TEXT HAS 1 DECUMENT  |   | Erroc. AS-Inv.                    |
|  | was:  | MAsset. Gir.:                     |
| INBOX.4 (#4785) TEXT:  | TELLT   | from two                          |
|  | 1 APR 86 47777 .  | kungen   119.                     |
| OO HO WFO  | FEDERAL BUTEAU<br>OF INVESTIGATION                        | Lefteratory: [1] Lefter Coun. [1] |
| DE MM  | OL THACOLOGY  | Cif. et Cons. B                   |
| O 071532Z APR 86   | 4245  | Toch. Servs.                      |
|  | 42/   | Treining Telephone Rm.            |
| FM MIAMI (47-NEW) (C-2) (C)  | i,  | Director's Sec'x                  |
| TO DIRECTOR IMMEDIATE  | EURTETUE NAIR CAMERAINEA                                  | T COINEC                          |
| (ATTENTION: S\$A   | FUGITIVE AND GOVERNMEN                                    | T CRIMES b6<br>b7c                |
| TIME (IM G) TANKERS TANKS  | INFORMATION CONTAINED                                     | _                                 |
|  | EIN IS UNCLASSIFIED<br>E 07-08-2009 BY 60324 UCBAW/DK/SBS | 1341                              |
| UNCLAS   | · ·   |                                   |
| UNSUBS; POSSIBLE IMPERSONATION OF  | F FBI SPECIAL AGENTS, ARRO                                | W AIRLĮNES -                      |
| VICTIM; OO: MIAMI  | 11  | Au /                              |
| RE WFO TELETYPE TO BUREAU,   | DATED APRIL 4, 1986.                                      |                                   |
| FOR INFORMATION BUREAU AND   |   | IABLE •                           |
| LOCATED FOR (FNU)'S  | OR HOW  | EVER,                             |
| REFERENCE TO LOCA  | TED AND REVEALED FOLLOWING                                | 1/2                               |
|  | - 163 - 56160 RROW AIRLINES, INTERVIEWED                  |                                   |
| FEBRUARY 20, 1986, CONCERNING CA   | SE ENTITLED, "ARROW ATR DC                                | 1986<br>8-63, GANDER,             |
| NEW FOUNDLAND, DECEMBER 12, 1985   | No. 1   | h7C                               |
| CRIMINAL MATTER; BUDED: FEBRUAR  |   |                                   |
|  |   |                                   |
| ي<br>چاپ موس مورد يو د ا   |   |                                   |
| 506  |   | 4                                 |
| Val. 12.   | .1  |                                   |
|  |   | . 621 Cro                         |
| NOTICE 23 THE CONTRACTOR OF TH | W. C. T. IA.  | 30 V                              |
| DEC 2.3  | V (   | 11/2                              |
| V.   | 02  | VER !                             |

PAGE TWO MM 47-NEW UNCLAS

DETAILS OF INTERVIEW CONDUCTED BY MIAMI CONTAINED IN LHM, DATED FEBRUARY 20, 1986, ENCLOSED WITH MIAMI AIRTEL TO DIRECTOR, DATED MARCH 3, 1986, UNDER MIAMI FILE 163A-4162, BUREAU FILE 163A-NEW.

ALSO, PRIOR COMMUNICATION ENCLOSED INTERVIEW OF FLORIDA, FEBRUARY 22, 1986, AND OTHERS.

BT

กรี่ยา

.

•

•

111

DATE 07-08-2009 BY 60324 UCBAWȦ̀DK/Š**¥**S FORMS. TEXT HAS 1 DOCUMENT FILES.INCOMING.DAY1-7.947 (#371)26 ET mba-01 2003 E=>c. C.O.Inv. Eco. AJ.LES 3 MAR 86 TEXT: VZCZCWF0006 Asst. Dir.: Adm. Cerus. RR HQ FEIL Roll OF INVESTIGATION DE WF0006 092 0345 ZNR UUUUU R 020345Z APR 86 OlPublic Alla FROM SAC, WASHINGTON FIELD OFFICE (47-0) Doc. Ment. Tech. Servs. DIRECTOR, FBI ROUTINE Training. Telephone Rm. ATTN: FUGITIVE AND GOVERNMENT CRIMES UNIT, CID Director's Sec'y OARROW. AIR ВТ UNCLAS UNSUBS: POSSIBLE IMPERSONATION OF FBI SPECIAL AGENT AIRLINES-VICTIM; 90:WFO 0N 4/1/86 (X)ATTORNEY, HUGHES, HUSBAND, REED, SUITE 300, 1201 PENNA. AVE., WASHINGTON, D.C. WAS CONTACTED BY WFO REGARDING INFORMATION HE PROVIDED TO b6 THE BUREAU INDICATING INDIVIDUALS MAX HAVE IMPERSONATED FBI b7C AGENTS IN CONTACTING ARROW THAT THIS FIRM REPRESENTS ARROW AIRLINES APR 16 1996 LITIGATION REGARDING THE MILITARY CHARTERED ARROW AIRLINE PLANE THAT CRASHED IN CANADA. STATED THAT HE HAD b6 b7C RECEIVED INFORMATION THAT FBI AGENTS WERE QUESTIONING ARROW

DEC 1 2 1986 K

PAGE TWO DE WF 0006 U N C L AS EMPLOYEES REGARDING HYDRAULIC SYSTEMS ON ARROW'S PLANES. REQUESTED ANY INFORMATION REGARDING ANY POSSIEL FBI INVESTIGATION. WAS ADVISED THAT THERE IS NO INVESTIGATION UNDERWAY BY THE WASHINGTON FIELD OFFICE REGARDING THE ARROW AIRLINE CRASH. HE WAS FURTHER ADVISED THAT HE SHOULD DIRECT ANY QUESTIONS REGARDING FBI INVESTIGATIONS OF ARROW AIRLINES TO THE ASSISTANT DIRECTOR CRIMINAL INVESTIGATION DIVISIONS, FBIHQ, IN ORDER TO DETERMINE IF ANY ACTIVE INVESTIGTION REGARDING ARROW AIRLINES IS CURRENTLY UNDERWAY IN ANY OTHER FIELD OFFICE. WAS ALSO ADVSIED THAT THE DEPARTMENT OF. TRANSPORTATION WOULD MOST LIKELY CONDUCT ANY INVESTIGATION OF AN AIRLINES CRASH. HE WAS ALSO ADVISESD THAT THE DEPARTMENT OF TRANSPORATION DOES EMPLOY SPECIAL AGENTS AND THAT THERE MAY BE SOME CONFUSION REGARDING THIS MATTER. INDICATED HIS INFORMATION WAS THIRD AND FOURTH HAND AND THAT HE IS NOT SURE IF THESE INVESTIGATIONS DID ACTUALLY REPRESENT THEMSELVES AS FBI AGENTS. HE INDICATED THAT HE

WOULD RECONTACT HIS SOURCE OF INFORMATION TO DETERMINE IF

.b6

PAGE THREE DE WF 0006 U N C L A S

THE INVESTIGATORS DID ACTUALLY REPRESENT THEMSELVES AS FBI

AGENTS. WILL RECONTACT WFO IF HE SUSPECTS THAT

ANY INDIVIDUAL ATTEMPTED TO IMPERSONATE A FEDERAL AGENT.

WFO TAKING NO FURTHE ACTION.

BT

#006

NNNN

b6 b7C

MIN-18 MARIE OF THE STATES OF THE

UNSUBS;

PÓSSIBLE IMPERSONATION OF

FBI SPECIAL AGENTS

ARROW AIRLINES - VICTIM

00: MIAMI

ARROW AIR
DC8-63,
GANDER, NEWFOUNDLAND,
DECEMBER 12, 1985;
FOREIGN POLICE COOPERATION,
GENERAL CRIMINAL MATTERS;

CLARKE.

The following is in response to Mr. Mintz' inquiry of 3/31/86 concerning the above-captioned possible impersonation matter:

on 4/1/86 and 4/4/86, the Washington Field Office contacted Attorney who advised that an Arrow Air Flight crew reportedly had been interviewed by FBI Agents in Miami, Florida, relative to its fatal crash of DC8-63 at Gander, b7C Newfoundland, on 12/12/85.

Based upon this information, it has been determined that the FBI did conduct a Foreign Police Cooperation (FPC) investigation in this matter pursuant to a to the Director, dated 12/31/85 (copy attached).

On 1/31/86,

Air, Miami, Florida, made available the names of a flight crew who could advise of the condition of DC8-63 during its round trip from Cologne, West Germany, to Cairo, Egypt, and return, during the period 12/11-12/85.

Subsequently, the Miami and San Francisco Divisions

and . The final results of our investigation have been disseminated by LHM to the Washington, D.C., and the Defense Intelligence Agency via liaison.

₹.•

OCT 08 1986

file

FINA DOUBE



## U.S. Department of Justice

## Federal Bureau of Investigation

In Reply, Please Refer to File No.

Miami, Florida February 20, 1986

ARROW AIR DC 8-63, GANDER, NEW FOUNDLAND, DECEMBER 12, 1985; FOREIGN POLICE COOPERATION -GENERAL CRIMINAL MATTERS

|               | Florida, telephone  | number  |          | voluntarily   |
|---------------|---------------------|---------|----------|---------------|
| appeared at t | he Fort Lauderdale, | Florida | Office o | f the FEDERAL |
| BUREAU OF INV | ESTIGATION (FBI).   |         |          |               |
|               |                     |         |          |               |

After having been advised of the identity of the interviewing official and the nature of the inquiry, he furnished the following information:

During December, 1985, he was employed by ARROW AIR (AA), Miami, Florida, as a aboard a DC 8 aircraft owned by that company, United States Registration 950 JW.

On December 11, 1985, he was the on that aircraft on two flights, the first departing Cologne, West Germany, at 1050 Greenwich mean time, arriving at Cairo, Egypt, at 1534 Greenwich mean time. The second flight was from Cairo to Cologne, departing Cairo at 2035 Greenwich mean time, arriving at Cologne at 0121 Greenwich mean time.

The only discrepencies on the aircraft that he was aware of during the course of those two flights were as follows:

- 1. The true air speed entry function on the Omega navigation system was inoperative.
- 2. The forward main cargo door had been tagged for deferred maintenance and had a sign affixed, "Do not open"; however, because of the amount of baggage on the Cairo to Cologne leg, the forward main cargo door was in fact open. The malfunction in the door which had caused it to be tagged concerned the counterweight pulley system. This meant that additional human muscle power was needed to secure the door, but after the cargo hold had been filled the door was in fact closed and properly secured. The door was secured at CAIRO INTERNATIONAL AIRPORT (CIA), by himself,

b6 b7C b7C



163-56160-1

FULUSURE

ALL INFORMATION CONTAINED HEREIN IS UNCLASSIFIED DATE 07-08-2009 BY 60324 UCBAW/DK/SBS